

OSM Bulkhead Feedthrough Cable Jack Direct Solder Attachment 1051001-1

408-4947 28 FEB 00 Rev O

EC 0990-0234-00

Instruction Sheet

CONNECTOR TYPE

OSM BULKHEAD FEEDTHROUGH CABLE JACK DIRECT SOLDER ATTACHMENT


CABLE TYPE

RG402/U .141 SEMI-RIGID COAXIAL CABLE

TOOLS REQUIRED:

FIXTURE BASE:2098-5208-54(T-4567) CLAMP INSERT: 2090-5207-54(T-4700-0 LOCATOR TOOL 2098-5213-02(T-948)

CONNECTOR





ASSEMBLY OPERATIONS


1.0 PREPARATION OF CABLE
1.1 INSERT SQUARED CABLE END INTO FIXTURE BASE
HOLE PATTERN 12.
1.2 PLACE SAM IN SAW SLOT AND CUT THROUGH OUTER
CONDUCTOR AND INTO DIELECTRIC MHILE ROTATING
CABLE.
1.3 REMOVE CABLE FROM FIXTURE AND FINISH CUTTING
DIEJECTRIC WITH CUTTING BLADE.

1.4

REMOVE CABLE FROM FIXTURE AND FINISH CUTTIF DIELECTRIC WITH CUTTING BLADE. BARE INNER CONDUCTOR BY PRYING CUT OUTER CONDUCTOR AND DIELECTRIC FROM CABLE. COMPLETE TRIMMING OF CABLE INNER CONDUCTOR TO DIMENSION SHOWN.

HOLE PATTERN FECTURE BASE T-45677 .110 土 .010 CABLE DELECTRIC

SHAPE INNER CONDUCTOR OF CABLE
1 FILE BLUNT END OF INNER CONDUCTOR
TO AN 85°-90° COME.



3.0 SOLDERING OF CABLE TO MOUSING SUB-ASSEMBLY
3.1 ASSEMBLE LOCATOR TOOL ONTO HOUSING SUB-ASSEMBLY.
3.2 INSERT PREPARED CABLE END ONTO PRE-ASSEMBLED CENTER CONTACT OF HOUSING AND BOTTOM, FIRMLY,
3.3 PLACE CONNECTOR ASSEMBLY INTO FIXTURE BASE AS SHOWN. (LOCATOR TOOL SHOULD REST ON FIXTURE BASE).
3.4 MAINTAIN CABLE FIRMLY SEATED IN HOUSING SUB-ASSEMBLY AND TIGHTEN CLAMP SCREW.
3.5 SOLDER WHERE SHOWN.

FIXTURE BASE SHOULD BE CLAMPED VERTICALLY IN VISE TO KEEP LOCATOR TOOL SEATED AGAINST FIXTURE BASE. NOTE:

