
SPECIFICATION CONTROL DRAWING



MATERIALS

- 1. INSULATION SLEEVE: Heat-shrinkable, radiation cross-linked modified fluoropolymer. Color: clear. Qty/kit: 2
- 2. BRAID: Tin-plated copper alloy. Qty/kit: 2
- 3. SOLDERSLEEVE: Qty/kit: 1

INSULATION SLEEVE: Heat-shrinkable, transparent blue, radiation cross-linked modified polyvinylidene fluoride. SOLDER PREFORM WITH FLUX AND THERMAL INDICATOR:

SOLDER: TYPE Sn63 per ANSI-J-STD-006.

FLUX: TYPE ROL1 per ANSI-J-STD-004.

THERMAL INDICATOR: Fusible ring, Melt point: 221°C.

MELTABLE RINGS: Environment resistant thermoplastic. Color: blue.

APPLICATION

1. This kit is used to provide an environmentally protected shield termination on a quadrax cable and two braids, having tin or silver-plated shields, and an insulation rated for at least 125°C.

Cable jacket diameter: 5.95 [0.235] max.

Cable shield diameter: 3.30 [0.130] min.

Conductor insulation diameter: 2.54 [0.100] max.

2. Temperature range: -55°C to +150°C.

tyco Electronics	300 Constitution Drive,		Ra	ychem	TITLE: QUADRAX CABLE SPLICE KIT			ICE KIT	
Unless otherwise specified dimensions are in millimeters. [Inches dimensions are shown in brackets]					DOCUMENT NO.: D-150-0332				
TOLERANCES: 0.00 N/A 0.0 N/A 0 N/A	ANGLES: N/A Tyco Electronics reserve this drawing at any time evaluate the suitability of application.		y time. Users s	hould	REV.: A		DATE: 22-Jun-06		
PREPARED BY: M.Foronda		DCR NUMBER: F D060138		REPLACES:		CAGE CODE : 06090	SCALE:	SIZE: A	SHEET: 1 of 2


© 2006 Tyco Electronics Corporation. All rights reserved.

If this document is printed it becomes uncontrolled. Check for the latest revision.


SPECIFICATION CONTROL DRAWING

INSTALLATION PROCEDURE


1. Prepare the cable as shown.



- 2. Application Equipment: Steinel HL1802E Heat Gun with a SolderSleeve reflector (Setting of 11 12)
- 3. Assembly Procedure
 - a) Slide the SolderSleeve onto the cable.
 - b) Slide the jumper braid over two of the conductors.
 - c) Place the insulation sleeve on top of the braid.



- d) Apply heat to the insulation sleeve until it completely recovers over the braid.
- e) Repeat steps 3b and 3c for the other two conductors.
- f) Fold the cable shield back over the jumper braids.



g) Position the SolderSleeve over the cable shield, the solder preform centered on the shield.

	and have the former the	
♥	and the second	

h) Apply heat to the center of the SolderSleeve until the solder melts, flows and wets the solder to the cable shield.

i) Apply heat to end of sleeve until rings melt and flow along cable jacket.

j) Repeat for other end of sleeve.

Unless otherwise specified dimensions are in millimeters. [Inches dimensions are shown in brackets]

DOCUMENT NO.:	DCR NUMBER:	REV.:	DATE:	SHEET:
D-150-0332	D060138	А	22-Jun-06	2 of 2

© 2006 Tyco Electronics Corporation. All rights reserved.

If this document is printed it becomes uncontrolled. Check for the latest revision.