

HarnWare Drawing Borders in Visio 2010




Contents


1	Intro	oduction	
2	Drawing Border		
	2.1	Outer Frame	
	2.2	Information Boxes	4
	2.3	Shape Sheet	6
	2.4	Insert Fields	9
	2.5	Drawing Properties	13
3	Stencils		
	3.1	New Stencil	14
	3.2	Existing Sheets Stencil	19
4	Other HarnWare Pages		
	4.1	Parts List	
	4.2	Wire List	25
	4.3	Wiring Schedule	26
	4.4	Labour Estimate	26
	4.5	All Other Pages	26
5	The Template		27
		Saving the Template	

1 Introduction

This manual instructs in how to create drawing borders using Visio 2010, and input fields into the border to enable the user to fill in drawing information such as title, drawn-by, etc. via a data input screen. The drawing border becomes a Visio Shape and the information entered is known as Shape Data (up to and including Visio 2003, Shape Data was known as Custom Properties). A HarnWare Drawing Border Properties function facilitates the completion of information boxes in all sheets in the drawing file if the user desires.







All other pages in the file such as Parts List, Wire List, and Labour Estimate etc. have unique names and do interface with HarnWare. They contain specific properties that enable HarnWare to recognise them and edit data associated with the drawing file. Pages can have different designs of border with a different number of information boxes but providing the fields are identified identically the Drawing Properties tool will operate on them. For example, the Labour Estimate page has less room for the information boxes so fewer are possible and these normally contain the basic drawing information. This manual also instructs in how to edit these pages in the Sheets stencils and HarnWare templates.

Important Information: Standard company specific A4 to A0 or A to E size drawing borders can be stored on a stencil with a name of the designers choosing. All other pages **must** be stored on a stencil called Sheets-Metric or Sheets-Imperial for HarnWare to operate correctly. It is recommended, however, that all drawing pages are stored on the Sheets stencils for simplicity. The Sheet stencils normally open with the standard HarnWare template.

This manual is written for users of Visio 2010 although the principles described apply to most versions of Visio with some minor variations.

2 Drawing Border


Use this procedure to create borders for all sizes of page from A4 to A0 or A to E. It is recommended that a start is made with A3 or B as the contents of this size can generally be made common to all page sizes. Some minor adjustments may be required but keeping as much commonality as possible across the sizes reduces work, minimises transcription errors and ensures the Shape Data remains constant, thus reducing the need to edit pages individually.

2.1 Outer Frame

Create the outer frame using the Rectangle Tool from the Drawing toolbar then select No Fill from the Fill menu. Check that Snap to > Grid is selected in the Tools > Snap and Glue




menu. This will ensure that the rectangle snaps to the grid and its size has a round number making it easier to populate with information boxes.



Allow a gap around the outside of the border as shown. At this stage it is recommended that a print trial be carried out and the border adjusted if the required output, either in size or centrality, is not achieved.


2.2 Information Boxes


Use the Rectangle Tool to create un-filled information boxes inside the drawing frame.




Select each box and type a title. In this example the text has been aligned top left. Note that the Format Text toolbar will need to be open to access vertical text alignment tools. Set the text height to suit.








At this stage a company logo can also be added and any other features that form part of the standard company border such as a tolerance box, drawing projection icon, XY coordinate graduations, notes, etc.





We now need to add text boxes to every box in the border that requires variable data to be edited from the Visio, Shape Data screen. Drag a text box in a position that will give the clearest legend and type a character – in this example an X. Set the text to the chosen height.



2.3 Shape Sheet


Once you have added the boxes, both for the headers and for the text, you need to group the whole page. Press Ctrl+A to Select All then Ctrl+G to group.






Select the border which is now a group and open its ShapeSheet. To do this click Developer> Show ShapeSheet or right click over the border to Show ShapeSheet.






When the Shape Sheet is open, right click a table header and insert the Shape Data section.




Once the Shape Data section has been added add one row for each editable text box. In this example 8 rows are required. To do this right click the first row in the Shape Data section and click Insert Row. Repeat until 8 rows have been created or use the F4 key to repeat last command.



Note that both Insert Section and Insert Row can be accessed via the Shape Sheet toolbar.







Re-label the Shape Data properties name from 'Row_1' to something more meaningful such as 'Title' or 'PartNumber'. Click the cell you wish to edit and type the new text in the Shape Sheet formula bar. Note:

- 1. The word 'Prop' remains so simply edit the name of shape data, e.g. 'Title'.
- 2. The name must be a single text string with no spaces, i.e. 'PartNumber'.
- 3. For the Label and Prompt columns insert the text between the quote marks.
- 4. For the Date property, change the '0' to '5' in the Type column. This will give a clickable calendar when editing Shape Data.

When you have finished editing, click the check box or hit the Return key to enter the edits into the Shape Sheet cell.






Edit the Events section of the Shape Sheet and enter "=DOCMD(1312)" into the 'EventDblClick' cell. This opens the Shape Data box when the drawing border is double clicked.




Close the Shape Sheet. Edits will be automatically saved.


2.4 Insert Fields

Select the drawing border then go to the Developer>Shape Name menu and record the name of the border shape. In this example it is Sheet. 5.







With drawing border still selected, select one of the text boxes previously added to the border information boxes.




Click on the Insert>Field menu to open the Field screen.








Choose the Custom Formula category and edit '=Sheet.5!Prop.Title' as shown below where Sheet.5 is the border name and 'Title' is the name given to the border information box.



Repeat the above procedure for all boxes and test by double clicking the border. If all's well the Shape Data box will open showing the label and prompt and the fields can be edited. Click OK and the data will be transferred to the drawing border.





To add page number and number of pages add text fields in the border as shown below.


Harness Assembly			
	DATE		
onnectivity	06/11/2012		
	PROJECT		
0-12345K/1	12345/12		
	ISSUE		
ADE	1		
POWER	PAGE X OF X		

Select each field in turn and use the Insert > Field command to insert Page Number and Number of Pages.











2.5 Drawing Properties

In order for the HarnWare, Drawing Properties tool to work all sheets need to have their class specified by using the Developer>Shape Name command and editing {Class=Drawing Border} in the Data 1 field. Developer>Shape Name can be accessed from the main toolbar.








3 Stencils


Drawing borders can be added to a new stencil or overwrite the borders in the Sheets-Metric stencil.

3.1 New Stencil

Open a new stencil using the Shapes tool from the Visio tool bar.



At this stage, edit the Shape Data by double clicking the border so that the text in the information boxes is replaced by a '-' as this will become the master shape for this size of drawing border.




Select the border and drag it into the new stencil. Right click the new icon in the stencil and select Edit Master>Edit Master Shape. Select the newly created border that is now open and 'Show Shape Sheet' as per Paragraph 2.3.


Move to the top of the Shape Sheet to the Shape Transform section and enter 'GUARD(ThePage!PageWidth/2)' in the 'PinX' cell and 'GUARD(ThePage!PageHeight/2)' in the 'PinY' Cell. This will snap the border to the centre of the page when dragged onto the drawing.




Close the Shape Sheet. Edits will be automatically saved. Save the stencil. Test by dragging the sheet into the drawing. It should snap to the centre of the page. Double click the border shape to open the Shape Data dialogue box.



Right click the new icon in the stencil and select Edit Master>Master Properties. Add a new name, a prompt and keywords and it is suggested that the two behaviour boxes are unchecked. The suggested icon size is 32 x 32, centre aligned.




Right click the new stencil tool bar icon and choose Properties. Edit the Title to the name chosen for the stencils




The icon can also be edited at this stage if desired. Right click the new icon in the stencil and select Edit Master>Edit Icon Image.






The Visio icon edit program is started and the icon can be edited to the desired design. This manual does not instruct in icon editing but once the program is open its use is self explanatory.




Right click the new stencil tool bar icon and choose Save As. Edit the file name to that chosen for the new stencil.



3.2 Existing Sheets Stencil


The simplest way of creating a company specific Sheets-Metric or Sheets-Imperial stencil is to edit the standard one shipped with HarnWare. For safety it is recommended that a copy of the standard stencil be taken and renamed before commencing with changes. The following procedure applies to all pages in the stencil.

With your new drawing border open in Visio, open the Sheets-Metric or Sheets-Imperial stencil.






Right click the stencil icon and select Edit Stencil.




Select the new drawing border and copy it. Right click the sheet icon that you are going to edit and select Edit Master>Edit Master Shape. In this example it is A3.



This will open the standard A3 sheet master shape. Select and delete it then paste in the new one, close and save the shape followed by saving the stencil. The icon can now be edited if desired. Test by dragging the new shape into the page. It should snap to the centre upon release of the mouse and by double clicking it Shape Data will open. Repeat for all page sizes.





4 Other HarnWare Pages

All other pages such as Parts List, Wire list, Labour Estimate etc. interface with HarnWare. If changes to these pages to make them company specific is desired, it is recommended that the





standard Sheets stencil and template be edited as follows and as described in Paragraph 3.2. The name of these pages is recognized by HarnWare and must not be edited.

4.1 Parts List


The HarnWare Parts List 1 opens as part of the standard HarnWare template and a Parts List border is stored in the Sheets stencil. When the Parts List tool is used, HarnWare populates the page in the template and opens further pages automatically if the number of parts exceeds the maximum for a single page. These are named Parts List 2, Parts List 3, etc. The border for the extra pages is taken from the Sheets Stencil and parts list lines are taken from the Miscellaneous Stencil, one for each in the Parts List. At present changes to column width, quantity of columns, or position of columns are not possible; contact Tyco Electronics for advice.

In order to retain the existing parts list page properties it is recommended that the existing parts list border be edited. It is also recommended that the outline and column headers etc. are retained. Note that a single parts list line is already positioned in the sheet and should be retained. Connection points, designated by a blue cross are also positioned at the top and bottom of the table and it is these that determine where the list starts and ends. If the new border information boxes are a different size to the standard then it is likely that the end connection point will have to be moved. Open the parts list group by right clicking on the Parts List 1 border in the template and click Group>Open Parts List.






Make the edits to the border as required. It may be possible to copy and paste the information boxes or parts of the information boxes from the sheets already edited.



When pasting into the group the copied shapes may not move. To solve this problem, close the group and open the Shape Sheet for the border. Find the Group Properties section and




change the 'DontMoveChildren' cell from TRUE to FALSE then close the Shape Sheet. Edit>Open Parts List to carry on editing the border.



Continue to edit the border in line with paragraph 2. Note:


- 1. Remember that the shape is already a group.
- 2. When adding property fields per Paragraph 2.4 you will find that the name of the sheet will not be Sheet.5 or similar but will have the sheet name, i.e. Parts List. To add the fields use Sheet.1 as the identifier in all cases, e.g. '=Sheet.1!Prop.Title'.

To move the End List Connection Point, select the Connection Point Tool from the Visio tool bar. The mouse pointer will feature a connection point.




In this example the End List Connection Point will need to be moved up the page to avoid Parts List lines overlapping the information boxes.





The new position should be about 5mm above the uppermost line in the information boxes in the X axis and can be anywhere across the page in the Y axis. Position the mouse pointer over the connection point, left click (the cross will turn pink and the Parts List page will automatically be selected) and drag the point to the new position.



When finished, leave a copy of the new page design in the template and following the procedure in Paragraph 3.2 replace the standard Parts List border with the new design in the Sheets stencil.

4.2 Wire List

Like the Parts List, the Wire List is stored in the Template and the Sheets stencil. The Wire List also has Start List and End List Connection Points to accommodate multiple pages of wiring information. Therefore the procedure for the Wire List is the same as for the Parts List



with the exception that the dimension of the End List Connection Point is 10mm above the uppermost line on the new information boxes.

4.3 Wiring Schedule

The Wiring Schedule also has Start List and End List Connection Points to accommodate multiple pages of wiring information. The Wiring Schedule is an alternative to a Wiring Schematic and is optional. Therefore it is not stored as a page in the template but only in the Sheets stencil but the procedure for creation is the same as for the Parts List.


4.4 Labour Estimate


The Labour Estimate page is stored only in the template and does not have a master in the Sheet stencil. It analyses the drawing and wire list and acts like spread sheet so it is strongly advised that, whilst editing the border, fields in the body of the page are not edited or moved. Shape Data fields can be added in the same way as all other borders, as described in Paragraph 2.4.

4.5 All Other Pages

The Notes, Design Checker, Marker, RoHS and Weight borders are not stored in the HarnWare template but all have masters in the Sheets stencils. To edit them, drag each shape onto a page, make the design changes in line with Paragraph 4.1 but once the new master shape in the stencil has been created and has been tested the original can be deleted as it does not form part of the template. Please Note:


1 The Checker and Notes borders have a box with no outline embedded in the master shape containing a text string that is used to define the start position and size of the text, and the extent. This should be left intact during editing.






2 The Weight and RoHS borders have a text line that defines start position, text height, row height, and column position and width. This should be left intact during editing.







5 The Template

At this stage you will have designed all new drawing borders and created masters in a new Sheets- Metric or Sheets-Imperial stencil. The masters will be groups with Shape Data fields specified such that double clicking the border and using the Visio Shape Data screen, or using the HarnWare Drawing properties tool will enable you to add drawing information into the border(s).

You will also have redesigned the Parts List, Wire List and Wiring Schedule borders by modifying the existing standard border but retaining the frame, headers and columns. You will have adjusted the End List Connection Points as required and you will have added shape data fields to match the new drawing borders. The Parts List and Wire List will have masters in the Sheets stencil and a page will also be in the Template. Both will have their first text line positioned in the page but not in the master and separate from the border shape. The wiring Schedule will have a master in the Sheets stencil.

The Notes, Design Checker, Marker, RoHS and Weight borders are not stored in the HarnWare template but all have masters in the Sheets stencils. You will have redesigned them by modifying the existing standard borders but retained the frame, headers, columns and text lines as appropriate. All borders will have a text string or text line defining text input requirements embedded in the shape.


5.1 Saving the Template

The standard HarnWare templates opened when creating a new harness drawing contain four stencils and four drawing pages. They are called HarnWare – Metric or HarnWare- Imperial. The stencils are Connectors, Adaptors, Miscellaneous and Sheets, and the pages are A3 Harness Drawing, Parts List, Wire List and Labour Estimate. The Sheets stencil contains all sizes of drawing page as well as the supplementary pages.



A new company specific template can now be saved with the new Sheets-Metric or Sheets-Imperial stencils included. Other edits to the template can be made at this time if required. The opening Harness Drawing page can be set to an alternative size or edits to the time synthetics in the labour sheet can be made to suit local working practises.

To save a new template go to Visio File>Save As, select Save as type and choose Template (*.vst). Choose your new template name and save in the folder C:/Program Files>HarnWare>Template.



When opening a File>New your template will be available for selection.

