# Tyco Electronics Substance Report

Kumar, Shashi
Dec 19, 2008

**The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.**

## General Properties

| | |
|---|---|
| **Part Name** | 17P MTA156 HDR ASSY FL RA LF |
| **Part Number** | 4-641207-7 |
| **Total Part Weight (g)** | 7.417578 |
| **Unit of Measure** | EA (each) |

**REPORTED CONTENT**

| Name | CAS Number | Weight (g) | Weight (%) |
|---|---|---|---|
| Unspecified Compliant Substance | Unspecified Compliant Substance | 2.549517 | 34.371287 |
| Manganese | 7439-96-5 | 0.002337 | 0.031501 |
| Copper | 7440-50-8 | 3.341385 | 45.046849 |
| Chromium | 7440-47-3 | 0.000047 | 0.000630 |
| Lead | 7439-92-1 | 0.003308 | 0.044599 |
| Contains No Reportable TE5081-2 Substances | TE5081-2-0506 | 0.000042 | 0.000563 |
| zinc | 7440-66-6 | 1.308398 | 17.639149 |
| Arsenic | 7440-38-2 | 0.000467 | 0.006300 |
| Nickel | 7440-02-0 | 0.030177 | 0.406829 |
| Tin | 7440-31-5 | 0.015998 | 0.215677 |
| Antimony oxide | 1309-64-4 | 0.148379 | 2.000370 |
| Antimony | 7440-36-0 | 0.000467 | 0.006300 |
| Iron | 7439-89-6 | 0.002337 | 0.031501 |
| Beryllium | 7440-41-7 | 0.000047 | 0.000630 |
| Mercury | 7439-97-6 | 0.000023 | 0.000315 |
| Cadmium | 7440-43-9 | 0.000467 | 0.006300 |
| Gold | 7440-57-5 | 0.009509 | 0.128195 |
| Cobalt | 7440-48-4 | 0.004673 | 0.063003 |
| **All (18 items)** | | | |
| Total | | 7.417578 | |