

CERTIFICATE OF COMPLIANCE

Certificate Number 20170616-E46765
Report Reference E46765-20030916
Issue Date 2017-JUNE-16

Issued to: TYCO ELECTRONICS CORP
2901 FULLING MILL RD
MIDDLETOWN, PA 17057 USA

This is to certify that representative samples of Switches, Appliance and Special Use - Component
See Addendum Page for Models


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:

Additional Information:

See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

The UL Recognized Component Mark generally consists of the manufacturer's identification and catalog number, model number or other product designation as specified under "Marking" for the particular Recognition as published in the appropriate UL Directory. As a supplementary means of identifying products that have been produced under UL's Component Recognition Program, UL's Recognized Component Mark: , may be used in conjunction with the required Recognized Marks. The Recognized Component Mark is required when specified in the UL Directory preceding the recognitions or under "Markings" for the individual recognitions.

Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for use as components of complete equipment submitted for investigation rather than for direct separate installation in the field. The final acceptance of the component is dependent upon its installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170616-E46765
Report Reference E46765-20030916
Issue Date 2017-JUNE-16

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

16342xx where xx is 07 to 17 with the prefix 0, 1, or 2 and the suffix 0 to 9

1977744-1, 2213763-1, 2213763-2, 2213763-3, 2213763-4, 2213763-5, 2213763-6, 2213763-7, 2213763-8, 2213764-1, 2213764-2, 2213764-3, 2213764-4, 2213764-5, 2213764-6, 2213764-7, 2213764-8, 2213764-9, 1-2213764-0, 1-2213764-1, 1-2213764-2, 1-2213764-3, 1-2213764-4, 1-2213764-5, 1-2213764-6, 1-2213764-7, 1-2213764-8, 1-2213764-9, 2-2213764-0, 2-2213764-1, 2-2213764-2, 2-2213764-3, 2-2213764-4, 2-2213764-5, 2-2213764-6, 2-2213764-7, 2-2213764-8, 2-2213764-9, 3-2213764-0, 3-2213764-1, 3-2213764-2, 3-2213764-3, 3-2213764-4, 3-2213764-5, 3-2213764-6, 3-2213764-7, 3-2213764-8, 3-2213764-9, 4-2213764-0, 4-2213764-1, 4-2213764-2, 4-2213764-3, 4-2213764-4, 4-2213764-5, 4-2213764-6, 4-2213764-7, 4-2213764-8, 4-2213764-9, 5-2213764-0, 5-2213764-1, 5-2213764-2, 5-2213764-3, 5-2213764-4, 5-2213764-5, 5-2213764-6, 5-2213764-7, 5-2213764-8, 5-2213764-9, 6-2213764-0, 6-2213764-1, 6-2213764-2, 6-2213764-3, 6-2213764-4, 6-2213764-5, 6-2213764-6, 6-2213764-7, 6-2213764-8, 6-2213764-9, 7-2213764-0, 7-2213764-1, 7-2213764-2, 7-2213764-3, 7-2213764-4, 7-2213764-5, 7-2213764-6, 7-2213764-7, 7-2213764-8, 7-2213764-9, 8-2213764-0, 2213765-1, 2213765-2, 2213765-3, 2213765-4, 2213765-5, 2213765-6, 2213765-7, 2213765-8, 2213765-9, 1-2213765-0, 1-2213765-1, 1-2213765-2, 1-2213765-3, 1-2213765-4, 1-2213765-5, 1-2213765-6, 1-2213765-7, 1-2213765-8, 1-2213765-9, 2-2213765-0, 2-2213765-1, 2-2213765-2, 2-2213765-3, 2-2213765-4, 2-2213765-5, 2-2213765-6, 2-2213765-7, 2-2213765-8, 2-2213765-9, 3-2213765-0, 3-2213765-1, 3-2213765-2, 3-2213765-3, 3-2213765-4, 3-2213765-5, 3-2213765-6, 3-2213765-7, 3-2213765-8, 3-2213765-9, 4-2213765-0, 4-2213765-1, 4-2213765-2, 4-2213765-3, 4-2213765-4, 4-2213765-5, 4-2213765-6, 4-2213765-7, 4-2213765-8, 4-2213765-9, 5-2213765-0, 5-2213765-1, 5-2213765-2, 5-2213765-3, 5-2213765-4, 5-2213765-5, 5-2213765-6, 5-2213765-7, 5-2213765-8, 5-2213765-9, 6-2213765-0, 6-2213765-1, 6-2213765-2, 6-2213765-3, 6-2213765-4, 6-2213765-5, 6-2213765-6, 6-2213765-7, 6-2213765-8, 6-2213765-9, 7-2213765-0, 7-2213765-1, 7-2213765-2, 7-2213765-3, 7-2213765-4, 7-2213765-5, 7-2213765-6, 7-2213765-7, 7-2213765-8, 7-2213765-9, 8-2213765-0, 2213766-1, 2213766-2, 2213766-3, 2213766-4, 2213766-5, 2213766-6, 2213766-7, 2213766-8, 2213766-9, 1-2213766-0, 1-2213766-1, 1-2213766-2, 1-2213766-3, 1-2213766-4, 1-2213766-5, 1-2213766-6, 1-2213766-7, 1-2213766-8, 1-2213766-9, 2-2213766-0, 2-2213766-1, 2-2213766-2, 2-2213766-3, 2-2213766-4, 2-2213766-5, 2-2213766-6, 2-2213766-7, 2-2213766-8, 2-2213766-9, 3-2213766-0, 3-2213766-1, 3-2213766-2, 3-2213766-3, 3-2213766-4, 3-2213766-5, 3-2213766-6, 3-2213766-7, 3-2213766-8, 3-2213766-9, 4-2213766-0, 4-2213766-1, 4-2213766-2, 4-2213766-3, 4-2213766-4, 4-2213766-5, 4-2213766-6, 4-2213766-7, 4-2213766-8, 4-2213766-9, 5-2213766-0, 5-2213766-1, 5-2213766-2, 5-2213766-3, 5-2213766-4, 5-2213766-5, 5-2213766-6, 5-2213766-7, 5-2213766-8, 5-2213766-9, 6-2213766-0, 6-2213766-1, 6-2213766-2, 6-2213766-3, 6-2213766-4, 6-2213766-5, 6-2213766-6, 6-2213766-7, 6-2213766-8, 6-2213766-9, 7-2213766-0, 7-2213766-1, 7-2213766-2, 7-2213766-3, 7-2213766-4, 7-2213766-5, 7-2213766-6, 7-2213766-7, 7-2213766-8, 7-2213766-9, 8-2213766-0, 2213767-1, 2213767-2, 2213767-3, 2213767-4, 2213767-5, 2213767-6, 2213767-7, 2213767-8, 2213767-9, 1-2213767-0, 1-2213767-1, 1-2213767-2, 1-2213767-3, 1-2213767-4, 1-2213767-5,



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170616-E46765
Report Reference E46765-20030916
Issue Date 2017-JUNE-16

1-2213767-6, 1-2213767-7, 1-2213767-8, 1-2213767-9, 2-2213767-0, 2-2213767-1, 2-2213767-2, 2-2213767-3, 2-2213767-4, 2-2213767-5, 2-2213767-6, 2-2213767-7, 2-2213767-8, 2-2213767-9, 3-2213767-0, 3-2213767-1, 3-2213767-2, 3-2213767-3, 3-2213767-4, 3-2213767-5, 3-2213767-6, 3-2213767-7, 3-2213767-8, 3-2213767-9, 4-2213767-0, 4-2213767-1, 4-2213767-2, 4-2213767-3, 4-2213767-4, 4-2213767-5, 4-2213767-6, 4-2213767-7, 4-2213767-8, 4-2213767-9, 5-2213767-0, 5-2213767-1, 5-2213767-2, 5-2213767-3, 5-2213767-4, 5-2213767-5, 5-2213767-6, 5-2213767-7, 5-2213767-8, 5-2213767-9, 6-2213767-0, 6-2213767-1, 6-2213767-2, 6-2213767-3, 6-2213767-4, 6-2213767-5, 6-2213767-6, 6-2213767-7, 6-2213767-8, 6-2213767-9, 7-2213767-0, 7-2213767-1, 7-2213767-2, 7-2213767-3, 7-2213767-4, 7-2213767-5, 7-2213767-6, 7-2213767-7, 7-2213767-8, 7-2213767-9, 8-2213767-0, 2213771-1, 2213771-2, 2213771-3, 2213771-4, 2213771-5, 2213771-6, 2213771-7, 2213771-8, 2213772-1, 2213772-2, 2213772-3, 2213772-4, 2213772-5, 2213772-6, 2213772-7, 2213772-8, 2213772-9, 1-2213772-0, 1-2213772-1, 1-2213772-2, 1-2213772-3, 1-2213772-4, 1-2213772-5, 1-2213772-6, 1-2213772-7, 1-2213772-8, 1-2213772-9, 2-2213772-0, 2-2213772-1, 2-2213772-2, 2-2213772-3, 2-2213772-4, 2-2213772-5, 2-2213772-6, 2-2213772-7, 2-2213772-8, 2-2213772-9, 3-2213772-0, 3-2213772-1, 3-2213772-2, 3-2213772-3, 3-2213772-4, 3-2213772-5, 3-2213772-6, 3-2213772-7, 3-2213772-8, 3-2213772-9, 4-2213772-0, 4-2213772-1, 4-2213772-2, 4-2213772-3, 4-2213772-4, 4-2213772-5, 4-2213772-6, 4-2213772-7, 4-2213772-8, 4-2213772-9, 5-2213772-0, 5-2213772-1, 5-2213772-2, 5-2213772-3, 5-2213772-4, 5-2213772-5, 5-2213772-6, 5-2213772-7, 5-2213772-8, 5-2213772-9, 6-2213772-0, 6-2213772-1, 6-2213772-2, 6-2213772-3, 6-2213772-4, 6-2213772-5, 6-2213772-6, 6-2213772-7, 6-2213772-8, 6-2213772-9, 7-2213772-0, 7-2213772-1, 7-2213772-2, 7-2213772-3, 7-2213772-4, 7-2213772-5, 7-2213772-6, 7-2213772-7, 7-2213772-8, 7-2213772-9, 8-2213772-0, 2316366-1 (AV1910PA12Q04), 2316366-2 (AV1910PAV24Q04), 2316366-3 (AV1910PB12Q04), 2316366-4 (AV1910PB24Q04), 2316366-5 (AV1910PG12Q04), 2316366-6 (AV1910PG24Q04), 2316366-7 (AV1911PA12Q04), 2316366-8 (AV1911PA24Q04), 2316366-9 (AV1911PB12Q04), 1-2316366-0 (AV1911PB24Q04), 1-2316366-1 (AV1911PG12Q04), 1-2316366-2 (AV1911PG24Q04), 1-2316366-3 (AV1920PA12Q04), 1-2316366-4 (AV1920PA24Q04), 1-2316366-5 (AV1920PB12Q04), 1-2316366-6 (AV1920PB24Q04), 1-2316366-7 (AV1920PG12Q04), 1-2316366-8 (AV1920PG24Q04), 3-2316366-0 (AV1910PA12T5Q04), 3-2316366-1 (AV1910PA24T5Q04), 3-2316366-2 (AV1910PB12T5Q04), 3-2316366-3 (AV1910PB24T5Q04), 3-2316366-4 (AV1910PG12T5Q04), 3-2316366-5 (AV1910PG24T5Q04), 3-2316366-6 (AV1911PA12T5Q04), 3-2316366-7 (AV1911PA24T5Q04), 3-2316366-8 (AV1911PB12T5Q04), 3-2316366-9 (AV1911PB24T5Q04), 4-2316366-0 (AV1911PG12T5Q04), 4-2316366-1 (AV1911PG24T5Q04), 4-2316366-2 (AV1920PA12T5Q04), 4-2316366-3 (AV1920PA24T5Q04), 4-2316366-4 (AV1920PB12T5Q04), 4-2316366-5 (AV1920PB24T5Q04), 4-2316366-6 (AV1920PG12T5Q04), 4-2316366-7 (AV1920PG24T5Q04), 2316531-1 (AV1910EA12Q04), 2316531-2 (AV1910EA24Q04), 2316531-3 (AV1910EB12Q04), 2316531-4 (AV1910EB24Q04), 2316531-5 (AV1910EG12Q04), 2316531-6 (AV1910EG24Q04), 2316531-7 (AV1911EA12Q04), 2316531-8 (AV1911EA24Q04), 2316531-9 (AV1911EB12Q04), 1-2316531-0 (AV1911EB24Q04), 1-2316531-1 (AV1911EG12Q04), 1-2316531-2 (AV1911EG24Q04), 1-2316531-3 (AV1920EA12Q04), 1-2316531-4 (AV1920EA24Q04), 1-2316531-5 (AV1920EB12Q04), 1-2316531-6 (AV1920EB24Q04), 1-2316531-7 (AV1920EG12Q04), 1-2316531-8 (AV1920EG24Q04), 3-2316531-0 (AV1910EA12T5Q04), 3-2316531-1 (AV1910EA24T5Q04),



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170616-E46765
Report Reference E46765-20030916
Issue Date 2017-JUNE-16

3-2316531-2 (AV1910EB12T5Q04), 3-2316531-3 (AV1910EB24T5Q04),
3-2316531-4 (AV1910EG12T5Q04), 3-2316531-5 (AV1910EG24T5Q04),
3-2316531-6 (AV1911EA12T5Q04), 3-2316531-7 (AV1911EA24T5Q04),
3-2316531-8 (AV1911EB12T5Q04), 3-2316531-9 (AV1911EB24T5Q04),
4-2316531-0 (AV1911EG12T5Q04), 4-2316531-1 (AV1911EG24T5Q04),
4-2316531-2 (AV1920EA12T5Q04), 4-2316531-3 (AV1920EA24T5Q04),
4-2316531-4 (AV1920EB12T5Q04), 4-2316531-5 (AV1920EB24T5Q04),
4-2316531-6 (AV1920EG12T5Q04), 4-2316531-7 (AV1920EG24T5Q04),
2316542-1 (AV1910DA12Q04), 2316542-2 (AV1910DA24Q04), 2316542-3 (AV1910DB12Q04),
2316542-4 (AV1910DB24Q04), 2316542-5 (AV1910DG12Q04), 2316542-6 (AV1910DG24Q04),
2316542-6 (AV1911DA12Q04), 2316542-8 (AV1911DA24Q04), 2316542-9 (AV1911DB12Q04),
1-2316542-0 (AV1911DB24Q04), 1-2316542-1 (AV1911DG12Q04), 1-2316542-2 (AV1911DG24Q04),
1-2316542-3 (AV1920DA12Q04), 1-2316542-4 (AV1920DA24Q04), 1-2316542-5 (AV1920DB12Q04),
1-2316542-6 (AV1920DB24Q04), 1-2316542-7 (AV1920DG12Q04), 1-2316542-8 (AV1920DG24Q04),
3-2316542-0 (AV1910DA12T5Q04), 3-2316542-1 (AV1910DA24T5Q04),
3-2316542-2 (AV1910DB12T5Q04), 3-2316542-3 (AV1910DB24T5Q04),
3-2316542-4 (AV1910DG12T5Q04), 3-2316542-5 (AV1910DG24T5Q04),
3-2316542-6 (AV1911DA12T5Q04), 3-2316542-7 (AV1911DA24T5Q04),
3-2316542-8 (AV1911DB12T5Q04), 3-2316542-9 (AV1911DB24T5Q04),
4-2316542-0 (AV1911DG12T5Q04), 4-2316542-1 (AV1911DG24T5Q04),
4-2316542-2 (AV1920DA12T5Q04), 4-2316542-3 (AV1920DA24T5Q04),
4-2316542-4 (AV1920DB12T5Q04), 4-2316542-5 (AV1920DB24T5Q04),
4-2316542-6 (AV1920DG12T5Q04), 4-2316542-7 (AV1920DG24T5Q04),
2317404-1 (AV1910RA12Q04), 2317404-2 (AV1910RA24Q04), 2317404-3 (AV1910RB12Q04),
2317404-4 (AV1910RB24Q04), 2317404-5 (AV1910RG12Q04), 2317404-6 (AV1910RG24Q04),
2317404-7 (AV1911RA12Q04), 2317404-8 (AV1911RA24Q04), 2317404-9 (AV1911RB12Q04),
1-2317404-0 (AV1911RB24Q04), 1-2317404-1 (AV1911RG12Q04), 1-2317404-2 (AV1911RG24Q04),
1-2317404-3 (AV1920RA12Q04), 1-2317404-4 (AV1920RA24Q04), 1-2317404-5 (AV1920RB12Q04),
1-2317404-6 (AV1920RB24Q04), 1-2317404-7 (AV1920RG12Q04), 1-2317404-8 (AV1920RG24Q04),
3-2317404-0 (AV1910RA12T5Q04), 3-2317404-1 (AV1910RA24T5Q04),
3-2317404-2 (AV1910RB12T5Q04), 3-2317404-3 (AV1910RB24T5Q04),
3-2317404-4 (AV1910RG12T5Q04), 3-2317404-5 (AV1910RG24T5Q04),
3-2317404-6 (AV1911RA12T5Q04), 3-2317404-7 (AV1911RA24T5Q04),
3-2317404-8 (AV1911RB12T5Q04), 3-2317404-9 (AV1911RB24T5Q04),
4-2317404-0 (AV1911RG12T5Q04), 4-2317404-1 (AV1911RG24T5Q04),
4-2317404-2 (AV1920RA12T5Q04), 4-2317404-3 (AV1920RA24T5Q04),
4-2317404-4 (AV1920RB12T5Q04), 4-2317404-5 (AV1920RB24T5Q04),
4-2317404-6 (AV1920RG12T5Q04), 4-2317404-7 (AV1920RG24T5Q04),
2317570-1 (AV2210EA12Q04), 2317570-2 (AV2210EA24Q04), 2317570-3 (AV2210EB12Q04),
2317570-4 (AV2210EB24Q04), 2317570-5 (AV2210EG12Q04), 2317570-6 (AV2210EG24Q04),
2317570-7 (AV2211EA12Q04), 2317570-8 (AV2211EA24Q04), 2317570-9 (AV2211EB12Q04),
1-2317570-0 (AV2211EB24Q04), 1-2317570-1 (AV2211EG12Q04), 1-2317570-2 (AV2211EG24Q04),
1-2317570-3 (AV2220EA12Q04), 1-2317570-4 (AV2220EA24Q04), 1-2317570-5 (AV2220EB12Q04),
1-2317570-6 (AV2220EB24Q04), 1-2317570-7 (AV2220EG12Q04),



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170616-E46765
Report Reference E46765-20030916
Issue Date 2017-JUNE-16

1-2317570-8 (AV222OEG24Q04), 3-2317570-0 (AV2210EA12T5Q04),
3-2317570-1 (AV2210EA24T5Q04), 3-2317570-2 (AV2210EB12T5Q04),
3-2317570-3 (AV2210EB24T5Q04), 3-2317570-4 (AV2210EG12T5Q04),
3-2317570-5 (AV2210EG24T5Q04), 3-2317570-6 (AV2211EA12T5Q04),
3-2317570-7 (AV2211EA24T5Q04), 3-2317570-8 (AV2211EB12T5Q04),
3-2317570-9 (AV2211EB24T5Q04), 4-2317570-0 (AV2211EG12T5Q04),
4-2317570-1 (AV2211EG24T5Q04), 4-2317570-2 (AV222OEA12T5Q04),
4-2317570-3 (AV222OEA24T5Q04), 4-2317570-4 (AV222OEB12T5Q04),
4-2317570-5 (AV222OEB24T5Q04), 4-2317570-6 (AV222OEG12T5Q04),
4-2317570-7 (AV222OEG24T5104), 2317655-1 (AV2510000T5Q04), 2317655-2 (AV2511000T5Q04),
2317655-3 (AV2520000T5Q04), 2317655-4 (AV2521000T5104), 2317656-1 (AV2510E112Q04),
2317656-2 (AV2510E124Q04), 2317656-3 (AV2510E312Q04), 2317656-4 (AV2510E324Q04),
2317656-5 (AV2510E512Q04), 2317656-6 (AV2510E524Q04), 2317656-7 (AV2510E612Q04),
2317656-8 (AV2510E624Q04), 2317656-9 (AV2510E712Q04), 1-2317656-0 (AV2510E724Q04),
1-2317656-1 (AV2511E112Q04), 1-2317656-2 (AV2511E124Q04), 1-2317656-3 (AV2511E312Q04),
1-2317656-4 (AV2511E324Q04), 1-2317656-5 (AV2511E512Q04), 1-2317656-6 (AV2511E524Q04),
1-2317656-7 (AV2511E612Q04), 1-2317656-8 (AV2511E624Q04), 1-2317656-9 (AV2511E712Q04),
2-2317656-0 (AV2511E724Q04), 2-2317656-1 (AV2520E112Q04), 2-2317656-2 (AV2520E124Q04),
2-2317656-3 (AV2520E312Q04), 2-2317656-4 (AV2520E324Q04), 2-2317656-5 (AV2520E512Q04),
2-2317656-6 (AV2520E524Q04), 2-2317656-7 (AV2520E612Q04), 2-2317656-8 (AV2520E624Q04),
2-2317656-9 (AV2520E712Q04), 3-2317656-0 (AV2520E724Q04), 3-2317656-1 (AV2521E112Q04),
3-2317656-2 (AV2521E124Q04), 3-2317656-3 (AV2521E312Q04), 3-2317656-4 (AV2521E324Q04),
3-2317656-5 (AV2521E512Q04), 3-2317656-6 (AV2521E524Q04), 3-2317656-7 (AV2521E612Q04),
3-2317656-8 (AV2521E624Q04), 3-2317656-9 (AV2521E712Q04), 4-2317656-0 (AV25213724Q04),
2317657-1 (AV2510EA12T5Q04), 2317657-2 (AV2510EA24T5Q04), 2317657-3 (AV2510EB12T5Q04),
2317657-4 (AV2510EB24T5Q04), 2317657-5 (AV2511EA12T5Q04), 2317657-6 (AV2511EA24T5Q04),
2317657-7 (AV2511EB12T5Q04), 2317657-8 (AV2511EB24T1Q04), 2317657-9 (AV2520EA12T5Q04),
1-2317657-0 (AV2520EA24T5Q04), 1-2317657-1 (AV2520EB12T5104),
1-2317657-2 (AV2520EB24T5Q04), 2317658-1 (AV2510M112Q04), 2317658-2 (AV2510M312Q04),
2317658-3 (AV2510M512Q04), 2317658-4 (AV2510M612Q04), 2317658-5 (AV2510M712Q04),
2317658-6 (AV2511M124Q04), 2317658-7 (AV2511M324Q04), 2317658-8 (AV2511M524Q04),
2317658-9 (AV2511M624104), 1-2317658-0 (AV2511M724Q04), 2-2317658-1 (AV2520M124Q04),
2-2317658-2 (AV2520M324Q04), 2-2317658-3 (AV2520M524Q04), 2-2317658-4 (AV2520M624Q04),
2-2317658-5 (AV2520M724Q04), 2-2317658-6 (AV2521M124Q04), 2-2317658-7 (AV2521M324Q04),
2-2317658-8 (AV2521M524Q04), 2-2317658-9 (AV2521M624Q04), 3-2317658-0 (AV2521M724Q04),
2317659-1 (AV2510MA12T5Q04), 2317659-2 (AV2510MA24T5Q04),
2317659-3 (AV2510MB12T5Q04), 2317659-4 (AV2510MB24T5Q04),
2317659-5 (AV2511MA12T5Q04), 2317659-6 (AV2511MA24T5Q04),
2317659-7 (AV2511MB12T5Q04), 2317659-8 (AV2511MB24T5Q04),
2317659-9 (AV2520MA1255Q04), 1-2317659-0 (AV2520MA24T5Q04),
1-2317659-1 (AV2520MB12T5Q04), 1-2317659-2 (AV2520MB24T5Q04)



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

