







REVISIONS					
P	LTR	DESCRIPTION	DATE	DWN	APVD
		SEE SHEET 1			

PACKAGING



25 PCS/Bundle






50pcs/Bag
drying agent: 1pcs/Bag



Number of label

- Importance of check:
1. Check whether the product is out of shape before packing.
 2. When packing, handle the product lightly to avoid product distortion.
 3. After packed, check whether there is any miss and whether the product is placed in the correct direction.
 4. If there are unfilled boxes, fill them with buffer materials.
 5. After the Carton is sealed, check whether the label is properly affixed, clean, legible, and whether the label content is correct.
 6. Carton size (604010011) : L340*W240*H230mm

Package materials			Packing Spec		
Items	P/N	QTY	PCS/Bag	Bag/Box	PCS/Box
Carton	604010011	1	50	40	2000
Small PE bag	840000511	40			
Waterproof bag	840000502	1			
Foam		2			
Drying agent	708040129	40			



Month
Carton Label



Carton Label

THIS DRAWING IS A CONTROLLED DOCUMENT.		DWN	 TE Connectivity			
		CHK				
DIMENSIONS:		APVD	NAME			
		PRODUCT SPEC				
		APPLICATION SPEC				
MATERIAL		WEIGHT	SIZE	CAGE CODE	DRAWING NO	RESTRICTED TO
			A2	C-		
			SCALE	SHEET	OF	REV