

ITEM	QTY	PART NUMBER	TE NUMBER
RELAY	1	FCAC-150-KR4	2-1617798-7
CONTACT PINS (5 PINS / PACK)	1	MIL-C-39092/22-192	6-1617806-2

NOTE: TOOL M89169/14-10 REQUIRED FOR REMOVAL/INSERTION
OF MIL-C-39092/22-192 CONTACT PINS.

REV. F
DCO 301590

~~COIL: @ 25°C
RESISTANCE _____
NOMINAL VOLTAGE _____
MUST OPERATE _____
MUST RELEASE _____~~

~~ENVIRONMENT:
VIBRATION _____ Hz TO _____ Hz @ _____ g's
SHOCK _____ g's _____ MS. DURATION
TEMPERATURE _____ °C TO _____ °C~~

~~NOTES: _____

_____~~


CUSTOMER DATA SHEET

~~_____~~
~~_____~~
~~_____~~
TERMINAL VIEW

~~CONTACT RATING: _____

_____~~

DR. RF 05/14/2013 CK. JMB 05/14/2013



CUST. _____ CATALOG ITEM _____
CUST. NO. _____ REV. _____

TE NUMBER
3-1617800-0

FCAC-150-KR4A